





















# ASSEMBLING INSTRUCTION

## DEXTER WORKING DESK 160

BEIGE - AMERICAN WALNUT




 GREY <b>BT3</b> <b>8 X</b>	 <b>M3</b> <b>34 X</b> Ø 6 MM X 1/2"	 <b>D</b> <b>36 X</b>	 <b>B</b> <b>24 X</b> Ø8 MM X 30 MM	 <b>BU</b> <b>1 X</b> BLACK	 <b>BT</b> <b>8 X</b>
 Ø19 MM <b>U1</b> <b>4 X</b>	 FULL OVERLAY <b>Q</b> <b>4 X</b>	 15 MM <b>BB7</b> <b>4 X</b>	 Ø 6 MM X 1 1/2" <b>L</b> <b>8 X</b>	 Ø15 MM X 12 MM <b>E1</b> <b>36 X</b>	 Ø 6 MM X 5/8" <b>M6</b> <b>20 X</b>
 <b>BV1</b> <b>1 X</b>		 <b>AT</b> <b>2 X</b>	 <b>R1</b> <b>R2</b> <b>L1</b> <b>L2</b> 350 MM <b>Z2</b> <b>2 X</b>		




 X 2     ±45 M


1




2




3




4



5




6




07

7




8




08

9




10




09

11




12





10

13




2X

15




2X

14




11


16




12



17




18




13

19



20



14